

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S3	8	(Hsi near Tsai near Chen).in.	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 17:01
S6	20	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3) and (bor\$3 or drill\$3) and rings and pins).ab.	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/13 16:35
S7	1199	((blank or work-piece or work adj piece) same (cutting or cuts or cut or mill\$3 or shear\$3) same (bor\$3 or drill\$3) same rings same pins)	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:00
S8	24	((blank or work-piece or work adj piece) with (cutting or cuts or cut or mill\$3 or shear\$3) with (bor\$3 or drill\$3) with rings with pins)	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 18:59
S9	20	S8 not S6	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 18:59
S10	9	((blank or work-piece or work adj piece) same (cutting or cuts or cut or mill\$3 or shear\$3) same (bor\$3 or drill\$3) same ((inner and outer) adj rings) same pins)	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:11

S11	249	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3 or shear\$3) and (bor\$3 or drill\$3) and ((inner and outer) adj rings) and pins)	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:23
S12	50	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3 or shear\$3) and (bor\$3 or drill\$3) and ((inner and outer) adj (cylinders or discs or disks)) and pins)	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:37
S13	130	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3 or shear\$3) and (bor\$3 or drill\$3) and ((inner and outer) adj (tubes or shafts)) and pins)	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:48
S14	127	S13 not S11	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:40
S15	5	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3 or shear\$3) and (bor\$3 or drill\$3) and ((inner and outer) adj (couplings or connectors)) and pins)	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:48
S16	385	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3 or shear\$3) and (bor\$3 or drill\$3) and ((inner and outer) adj (rings)))	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:45

S17	136	S16 not S11	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:45
S18	6	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3 or shear\$3) and (bor\$3 or drill\$3) and ((inner and outer) adj (couplings or connectors)))	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:48
S19	265	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3 or shear\$3) and (bor\$3 or drill\$3) and ((inner and outer) adj (tubes or shafts)))	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/12 19:48
S20	135	S19 not S13	US-PGPUB ; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/13 16:35

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	9	((blank or work-piece or work adj piece) and (cutting or cuts or cut or mill\$3) and (bor\$3 or drill\$3) and rings and (rods or tubes or pins) and (cavities or recesses or holes or openings)). clm.	US-PGPUB	OR	ON	2006/01/13 16:41

Interference Search HC 1/13/06